



**UNDERGROUND STORAGE  
TANK INSPECTION REPORT**  
INDIANA DEPARTMENT OF  
ENVIRONMENTAL MANAGEMENT

Inspector's Name:	John Gunter
Date:	2/10/2015
Time In:	2:00 PM
Time Out:	3:00 PM
Inspection Type:	Initial

**General Information**

Facility Information	
Facility Name	Circle K #2293
Facility Location	4841 N PENNSYLVANIA ST Indianapolis, IN 46205, Marion County
Facility Mailing Information	315 Commons Mall Columbus, IN
Owner Information	
UST Operator Certificate [329 IAC 9-9]	Name: Compliant with IDEM'S UST "C" Operator Training in accordance w 329 IAC 9. Certification Expiration Date:

**Operating Information**

Facility Registration Number	202
GPS Location Collected	<input type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Previously Collected
Financial Assurance Financial Responsibility [329 IAC 9-8]	Unknown
Number of Registered Tanks	3
Number of Compartmented USTs	

**General Comments**

--

**Tank Information**

Tank #	Contents	Status	Install Date
ID	Dimensions	Capacity	Contents
Corrosion Protection			Anode Test
Tank		Piping	
Last Tank Corrosion Test		Last Piping Corrosion Test	

Tank	Release Detection	Spill Protection
	Piping	
		Overfill Protection

Inspection Results/Action	
Inspection Results:	- No statute or rule violations
Facility Status:	
Documents and Photos Comments:	
Written Summary of Inspection:	
1. Empty tank 1 fill spill bucket of product, which is filled to top of containment. 2. Investigate dispenser #1/2 for possible leak of product and repair as needed.	



# UNDERGROUND STORAGE TANK INSPECTION REPORT

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT  
 Office of Land Quality, UST Section  
 100 N. Senate Avenue  
 Indianapolis, IN 46204-2251  
 Telephone: (800) 451-6027 or (317) 234-4112

## NOTICE OF FINDINGS

This is to notify you that on 2/10/2015 a site inspection for Facility Identification # 202, located at 315 Commons Mall, was conducted by the undersigned representative of the Indiana Department of Environmental Management (IDEM), Office of Land Quality, Underground Storage Tank (UST) Section.

### Site Inspection Findings:

Based on all the information obtained during the site inspection, this facility :

- DOES MEET the equipment, operating and maintenance requirements set forth in Indiana's UST Rule 329 IAC 9.
- DOES NOT MEET the equipment, operating and maintenance requirements set forth in Indiana's UST Rule 329 IAC 9  
 [see possible additional attachments].
- Presented Potential Violations were observed and may require further investigation(s).  
 [see possible additional attachments].
- Presented Other Compliance Needs and UST System Recommendations [additional comments may be attached]:

1. Empty tank 1 fill spill bucket of product, which is filled to top of containment. 2. Investigate dispenser #1/2 for potential leak of product and repair as needed.

.....  
 As a Facility Representative, I certify receipt of the Inspection Report of the indicated site inspection above and that significant details have been verbally communicated to the undersigned. In accordance with IC 13-14-5-4, matters not evident to IDEM at the time of the inspection, might not be included in either the verbal or written Inspection Report.

### Facility Representative:

Printed Name	Signature	Contact Number	Email	Date
John Gault	for Sheikh Cox			

### UST Compliance Inspector:

Printed Name	Signature	Contact Number	Email	Date
John Gault	John Gault	605 4669	jgault@idem.in.gov	2/10/2015

### Compliance Assistance:

In addition, compliance education links and materials can be found by visiting IDEM's UST web site at <http://www.in.gov/idem/4999.htm>, Compliance and Technical Assistance Program (CTAP) at <http://www.in.gov/idem/ctap> and the United States Environmental